





"The Overview Report of S-band Ground Station Verification and Operation for Lean

Satellite, HORYU-IV"

BONSU Benjamin, TATSUO Shimizu, HORYU-IV Project Members, CHO Mengu

Kyushu Institute of Technology

Laboratory of Spacecraft Environment INteraction Engineering (La SEINE)

October 19, 2016









- 1. Introduction
- 2. About of HORYU-IV Lean Satellite
- 3. Overview of S-band Ground Station
- 4. On-Ground Ground Station Verification Test Results
- 5. HORYU-IV Operation Status Report
- 6. On-Orbit Ground Station Verification Test Results
- 7. Conclusions and Lesson Learned




Introduction



- ✓ Small/micro/nano/pico satellite.
- ✓ Untraditional risk-accepting development methodology.
- ✓ Low-cost and fast-delivery.
- Lean-satellite mostly developed by universities .
 - ✓ Launch into Low Earth Orbit (LEO) for educational and research purposes
 - ✓ Utilize amateur VHF/UHF bands for space
 - \checkmark ground communication
 - ✓ Utilize data throughput of 1200kbps and 9600kbps
 - Limited time window of communication







Kyutech


https://www.google.co.jp/

As universities Lean satellite missions becomes sophisticated demand for higher data throughput and higher frequency for space – ground communication are arising




About HORYU-IV Project








HORYU-IV Team




HORYU-IV S-band Communication Requirements








Overview of S-band Ground Station



Developed and Installed by ELM and Microlab Comapnines









On-Ground S-band Ground Station Verification Results




Environmental Interference Test







Location: General Research Building 1 rooftop





Environmental Interference Results








Link Margin : 20.2dB




Rooftop

Results of "on-ground"S-band receiver data rate results





Result: 46kbps > Requirement: 38kbps PASSED







HORYU-IV Operation Status Report



First Day: HORYU-IV operation











"On-Orbit" Ground Station Verification Results







Discovered Problems Reasons



O HORYU-IV attitude was not stabilized (passive control) to orient transmitter antenna to ground.


OS-band receiver system and its interface could not correct Doppler shift.



Doppler shift impact on data reception


Frequency shift due to Doppler effect


10/19/2016




No Doppler effect

Kyutech





HORYU-IV Stabilization impact on data reception




10/19/2016 Kyushu Institute of Technology **Kyutech**




HORYU-IV "on-orbit" Link Margin Analysis Results after Stabilization





On-orbit margin ≈ **on-ground margin**



Link Margin : 19.62dB




HORYU-IV Image Data Results




Main mission image data **before** Doppler shift correction and satellite stabilization



Main mission image data **after** Doppler shift correction and satellite stabilization



Main mission data quality improved





Training of HORYU-IV Operators















Conclusion



- O S-band ground station can able to downlink HORYU-IV main mission data to contribute to scientific research
- **O** Lean satellites communication using Wi-Fi frequency range is possible.
- **O** Modification of S-band ground station configuration corrected Doppler shift and improved data reception
- **0** Passive attitude can severely impact signal strength and makes data reception difficult
- O Received data rate could satisfied the S-band communication requirement 10/19/2016



Lessons Learned



Overify ground station performances through long distance test prior to satellite launch

OPerform ground station testing with real satellite article

O Do not only rely on manufacturers if they have little experience, "Trust but verify" strategy



Lessons Learned



OImplement already-proven commercial off the shelf communication systems


O Do not underestimate the importance of Doppler shift. Check the compliance with the Doppler shift before the launch











Laboratory of Spacecraft Environmental Interaction Engineering



http://cent.ele.kyutech.ac.jp/index_e.html http://laseine.ele.kyutech.ac.jp/english/







QUESTIONS AND COMMENTS





Appendix



Software developed for HORYU-IV downlink operations



3 OPERATION AND ACTIVITI	ES INTERFACE	UPLINK LOG INTERFACE	Form1	- 0
lighei Senai Port COME in Connected Message: Successfully sent (17/39/2011 2014) AME Massie Salar Anne Explorement - HASA - AA-10-01-01-	AU-0-0-0-0	Power and mission high BATE/2011 B1222 PM Wassion Wade - Series OFF - HZA- Ad-49-49-19-49-49-49-49-49-49-49	1024	Ethemet Stream: 50 [segment/s]
Select Congori COM		(2/17/2018 01104 PM) Mauran Node - Delan GFT - H/ZA - AA-19-00-10-02-01-04-03-05-05-05-05-05-05-05-05-05-05-05-05-05-	A State Stop RCV-Ais ONLINE	Detected PreAmble: 0 [%]
Tolar Anna Connerent Monore - Auto Massee - Big Agen Mussee - CAMERA Massee - DAD Massee - A	000 Mixee 000 System Del MIX Connerd Mixion Durol	(8/19/2015 01367 PM) Mission Node - Camera Latitude - AA-F7-F7-60-10-00-00-00-00-00-00-00-00-00-00-00-00	Buffer Usage: 47[kB]	Save as:C:\Users\Sband\Google
S-Band Process (OBC and S-band Mode)		[Operator Line Field] in Departure Person and a low of the Uperator Line (for the Uperator Line (for 1) [D/13/2011 k11617 PM] Mission Hode - Celary OFF - Staty - Adv-Bot-Ho-Ho-Ho-Ho-Ho-Ho-Ho-Ho-Ho-Ho-Ho-Ho-Ho-	er Excavate	
1- Initial operation check v Sband Configration () () Address C ()	•			
Address A 0 0 Reserve 0	* *	MESSAUE ALERI UPDALE	Applying Bit Shift Error Correction: Making Index Correction:	
Address B 0 🗘	TRANSMIT	Please enter message for next operator BENJAMEN Please, perform the operational plan	Bit Shift Flip Collected Num: 0, CallSign: , Mem: 00 , Adr: 00 00 , Si Num: 1, CallSign: JG6YBW HORYU4>JG6Y	ize: 2816, CRC: 0F E1 ERROR (BW KYUTECH, Mem: 24, Adr: 33 90 , Size: 4096, CRC: 0F E1 GOOD (BW KYUTECH, Mem: 24, Adr: 33 A0 , Size: 4096, CRC: 0F E1 GOOD
O S-band Downlink O Transponder		Sat Loe Conera Mosion: AA 40 00 02 07 03 00 84 C4 EE S-band Downleik)	Num: 3, CallSign: JG6YBW HORYU4>JG6Y Num: 4, CallSign: JG6YBW HORYU4>JG6Y Num: 5, CallSign: JG6YBW HORYU4>JG6Y	/BW KYUTECH, Mem: 24, Adr: 33 B0, Size: 4096, CRC: 0F E1 GOOD /BW KYUTECH, Mem: 24, Adr: 33 C0, Size: 4096, CRC: 0F E1 GOOD /BW KYUTECH, Mem: 24, Adr: 33 D0, Size: 4096, CRC: 0F E1 ERROR /BW KYUTECH, Mem: 24, Adr: 33 E0, Size: 4096, CRC: 0F E1 GOOD
			Sdeit Num: 8, CallSign: JG6YBW HORYU4>JG6Y Num: 9, CallSign: JG6YBW HORYU4>JG6Y	(BW KYUTECH, Mem: 24, Adr: 33 F0, Size: 4096, CRC: 0F E1 GOOD (BW KYUTECH, Mem: 24, Adr: 34 00, Size: 4096, CRC: 0F E1 GOOD (BW KYUTECH, Mem: 24, Adr: 34 10, Size: 4096, CRC: 0F E1 GOOD (VEW KYUTECH, Mem: 24, Adr: 34 20, Size: 4096, CRC: 0F E1 GOOD

S-band Decoder Interface

S-band Decoder Analysis Interface



10/19/2016

Doppler compensation software



38

ΣS

693,730408

5646.690996

-10369.104763

11827.286868

-1604.551146

Satellite Status Manual Control \times Doppler Compensator Ver1.0 Calculation Results IP Setting Name HORYU-IV 6052 Start 192.168.1.254 ELM IP Address Port Azm 97.004064 ICOM IP Address 192,168,1,10 Port 10001 Stop EIv. -61.248026Lat -23.934264Upscaling Setting Lon -111.8099532nd Prediction 20 ERR: -99 \sim Alt. 575.774383 Vlc. ELM: 2400291308.92996 My Freq: 2400291283 [Hz] Doppler Caliculation ICOM 9500 Doppler Friguency Controller, TS 2016 2400300000 Fra Hz Terminal IP Address is 192,168,1.40 Get Refereence Frequency (1) Run ELM Antenna Controller and open Satellite Infomation Window (2) Connect ELM Antenna Controller and Lantronix Convertor ManuTrack (3) Pless Stat! Connecting ELM Antenna Controller (192.168.1.254)... PointSat (One Shot) ELM Antenna Controller is Online Track This Satellite Now (Real Time, Coarse) Connecting ICOM ICR9500 (192.168.1.10)... ICOM ICR9500 is Online Doppler compensation software developed to operate on the receiver PC

ECEF Coordn(Y) -6151.2391217.566040 ECEF Coordn(Z) -2821.121057ドップラー周波数 2400274836.117961 StopTrack Close Doppler compensation software developed by ELM company to integrate with the ICOM-R9500 receiver

ENU Coordn(X)

ENU Coordn(Y)


ENU Coordn(Z)

ENU Coordn(R)

ECEF Coordn(X)











After modification analysis results





Kyutech


La SEINE	Cont	• • • • •
Status of AVC motoe mission downlink data analysis	Average value obtained	Comments
Average Information Bit error rate (BER)	9.98139881 x 10 ⁻⁰⁶	BER = Ei /Tp
Average received Data rate (Dr)	40.2kbps	Dr = (Gp /T) / 1000
Average Packet lost (P_L)	48.73%	$P_{L} = (Ep - Tp)/Ep \times 100$
Average quality data reception (Qd)	86.4%	Qd=(Gp/ Ep) x100
Analyzed average error bits from Error packets (Ei)	34766848 bits	Estimated average error bits obtained error packets decoded data



Before modification



La SEINE		
Status of AVC motoe mission downlink data analysis	Average value obtained	Comments
Average expected Packets (Ep)	512 packets 1packet = 4096 bytes	Average expected packet to be received from satellite
Average total packets received (Tp)	262.5 packets (8601600)	Average total packets recorded from decoder analysis
Average good packets received (Gp)	59.75 packets (1957888 bits)	Average good packets recorded from decoder analysis
Average error packets received (Er)	202.75packets	Average error packets recorded from decoder analysis
Average time for Data reception (T)	360 seconds	Approximate time of data reception





Cont.....



Status of AVC motoe mission downlink data analysis	Average value obtained	Comments
Average Information Bit error rate (BER)	9.98139881 x 10 ⁻⁰⁴	BER = Ei /Tp
Average received Data rate (Dr)	5.4kbps	Dr = (Gp /T) / 1000
Average Packet lost (P_L)	48.73%	$P_{L} = (Ep - Tp)/Ep \ x \ 100$
Average quality data reception (Qd)	11.66%	Qd=(Gp/ Ep) x100
Analyzed average error bits from Error packets (Ei)	8600 bits	Estimated average error bits obtained error packets decoded data



Results

La SEINE	
A write Horn B.Black H	Fri 2016 Feb 19 14:23 MR 2,4003015 GHz orm -91.63 dBm
SPAN 500.0 kHz	
50kHz 2.4003GH	Iz center
10dBm frequ	
manaphana	When of the provide of the Mapon
V 10 kHz VIW 10 kHz SMP 20	STVH 500.0 MHz
Spectrum Analyzer Results	Obtained Value
Spectrum Analyzer Results Noise floor level (N)	ATT 0 dB
	Obtained Value
Noise floor level (N) Received Signal Strength	Obtained Value -105Bm

Link Margin Analysis Results

Link Margin = Received Eb/No – Required Eb/No Required Eb/No : 11.5dB Transmitted Bit Rate: 100kbps (50dBHz)

Received Eb/No (dB) = C/N (received)
- Transmitted Bit Rate + Bandwidth **Received Eb/No (dB)** = 13.37 - 50 + 51.4


Received Eb/No (dB) = 14.77dB *Link Margin (dB)* = 14.77 -11.5 *Link Margin* = 3.27dB

- Link Margin of 3.27dB obtained could not satisfy the design requirements.
- 3.27dB margin means the ground station can able to tolerate additional attenuation and still can decode the downlink data.
























C = -100.2 dBm - coupler lossC = -100.2 dBm + 10 dB*C* = -90.2*dBm C/N* = *29.72dB* Link Margin Analysis Results *Link Margin* = Received Eb/No – Required Eb/No Required Eb/No: 11.5dB Transmitted Bit Rate: 100kbps (50dBHz) **Received Eb/No (dB)** = C/N (received) -Transmitted Bit Rate + Bandwidth *Received Eb/No (dB)* = 29.72 – 50 + 51.4 *Received Eb/No (dB)* = 31.12dB *Link Margin (dB)* = 31.12 -11.5 *Link Margin* = 19.62**dB**





10/19/2016 https://en.wikipedia.org/wiki/Bit_error_rate#/media/File:PSK_BER_curves.svg






Feed horn Configuration





①RHCP/LHCP switching relays
②RX Test Signal Input for directional couplers
③LNA 1
④Isolators
⑤LNA 2
⑥Isolators



2400.3MHz BPF
 RX signal BPF IN
 RX signal BPF OUT
 RX signal OUT
 RX TEST signal 2400.3MHz IN


10/19/2016

La SEINE

Kyutech

Kyushu Institute of Technology

Schematic of S-band GS Configuration





APPRECIATION





Congratulations Prof. Mengu Cho

Dish Antenna Gain Measurement



La SEINE



APPRECIATION





Congratulations Prof. Mengu Cho!